



TOP



BOTTOM

DETAIL A



45° CHAMFER
BOTH SIDES
ENTIRE LENGTH OF
EDGE CONNECTOR
CHAMFER MUST BE FREE OF
CUTTING BURRS

