

Company	Trenz Electronic GmbH
PCN Number	PCN-20231106
Title	TE0706-03 BOM Change
Subject	BOM Change
Issue Date	2023-12-07

1 Products Affected

This change affects all Trenz Electronic TE0706-03 with a serial number greater than 841842.

2 Changes

2.1 #1 Removed VG96 connector (J6) from BOM.

Type: BOM Change

Reason: Improve manufacturing process.

Impact: Connector no longer available within product. If needed, connector needs to be ordered separately (Trenz article number 21545).

3 Method of Identification

The model code and revision number (TE0706-03) are printed on the top side of the PCB. The serial number is written at the QR-code on the top side label.

4 Production Shipment Schedule

For further help please contact us.

5 Contact Information

If you have any questions related to this PCN, please contact Trenz Electronics Technical Support at

- forum.trenz-electronic.de¹
- wiki.trenz-electronic.de²
- support@trenz-electronic.de³ (subject = PCN-20231106)
- phone
 - national calls: 05741 3200-0
 - international calls: 0049 5741 3200-0

6 Disclaimer

Any projected dates in this PCN are based on the most current product information at the time this PCN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Trenz Electronic sales office, technical support or local distributor.

This PCN follows JEDEC Standard J-STD-046.

¹ <http://forum.trenz-electronic.de/>

² <http://wiki.trenz-electronic.de/>

³ <mailto:support@trenz-electronic.de?subject=PCN-20231106>