

Company	Trenz Electronic GmbH
PCN Number	PCN-20200121
Title	TEB0911-04-* SO-DIMM Socket Change
Subject	BOM change
Issue Date	2020-01-21

Products Affected

This change affects all Trenz Electronic TEB0911 baseboards of Revision 04: TEB0911-04-XXXXXXX

Changes

#1 Replaced SO-DIMM DDR4 socket by B030-2604-60X1-ZHF

Type: BOM Change

Reason: Improve availability.

Impact: None.

Method of Identification

Boards with serial number greater than 606195 (number on white QR-Sticker) are assembled with the new SO-DIMM socket.

Production Shipment Schedule

From February 2020, after old stock is gone.

Contact Information

If you have any questions related to this PCN, please contact Trenz Electronics Technical Support at

- forum.trenz-electronic.de
- wiki.trenz-electronic.de
- support@trenz-electronic.de (subject = PCN-20200121)
- phone
 - national calls: 05741 3200-0
 - international calls: 0049 5741 3200-0

Disclaimer

Any projected dates in this PCN are based on the most current product information at the time this PCN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Trenz Electronic sales office, technical support or local distributor.

This PCN follows JEDEC Standard J-STD-046.