

<b>Company</b>	Trenz Electronic GmbH
<b>PCN Number</b>	PCN-20200818
<b>Title</b>	KK0807-02 to KK0807-02A Hardware Revision Change
<b>Subject</b>	Hardware Revision Change
<b>Issue Date</b>	2020-10-02

## 1 Products Affected

---

This change affects all KK0807-02:

<b>Affected Product</b>	<b>Replacement</b>
KK0807-02	KK0807-02A

## 2 Changes

---

### 2.1 #1 Added four M3 mountig holes.

---

**Type:** Hardware change


**Reason:** Request for screwed mounting of cooler on heatspreader.

**Impact:** The heatspreader is compatible with cooler KK0001-01.

## 3 Method of Identification

---

Models with 4 additional threads are revision 02A.



## 4 Production Shipment Schedule

---

The new revision 02A is available from September 2020, after old Stock is gone. If you still need revision 02 please contact us.

## 5 Contact Information

---

If you have any questions related to this PCN, please contact Trenz Electronics Technical Support at

- [forum.trenz-electronic.de](http://forum.trenz-electronic.de)<sup>1</sup>
- [wiki.trenz-electronic.de](http://wiki.trenz-electronic.de)<sup>2</sup>
- [support@trenz-electronic.de](mailto:support@trenz-electronic.de)<sup>3</sup> (subject = PCN-20200818)
- phone
  - national calls: 05741 3200-0
  - international calls: 0049 5741 3200-0

## 6 Disclaimer

---

Any projected dates in this PCN are based on the most current product information at the time this PCN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Trenz Electronic sales office, technical support or local distributor.

This PCN follows JEDEC Standard J-STD-046.

---

<sup>1</sup> <http://forum.trenz-electronic.de/>

<sup>2</sup> <http://wiki.trenz-electronic.de/>

<sup>3</sup> <mailto:support@trenz-electronic.de?subject=PCN-20200818>